FIATALLE NORTH AMERICA



July 16, 1985

SPC #1671205008 Sangamen Co. Sefld/Fiat - Allis

JUL 17 1385

Mr. Rick Lanham Illinois Environmental Protection Agency 4500 S. Sixth Street Springfield, Illinois 62706

Dear Mr. Lanham:

Per our conversation concerning our plating operation, please find enclosed the analysis results of the tank samples. We have not received the results of the sump analysis but I will forward copies when I receive them.


If you have any questions or desire further information concerning this matter, please contact me at (217) 789-3035.

Sincerely,

Hurley R. Ballenger Plant Engineer

HBallenger/da

#6 Meadow Heights Professional Park Collinsville, IL 62234 (618) 344-1004



June 17, 1985

REPORT #19-5

Andrews Environmental Engr., Inc. Project: Special Waste Testing

1320 South Fifth

Springfield, IL 62703

Fiat Allis

Springfield

ATTN: Mr. Douglas Andrews

Sample received: 06/03/85

Sample ID Sample Date

Lab ID #

Plating Tank #1

5/31/85

50603-10

ANALYSIS RESULTS

Hα Cyanide (Total) Sulfide (Total)

10.4 566 mq/kg mg/kg

E P Toxicity

PARAMETER	CONCENTRATION in EXTRACT	
Arsenic Barium Cadmium Chromium, Total Lead Mercury Selenium Silver	<pre><0.005 1.1 0.35 0.05 0.08 <0.001 <0.005 <0.01</pre>	mg/1 mg/1 mg/1 mg/1 mg/1 mg/1

These tests were conducted in accordance with "Test Methods for Evaluating Solid Waste, Physical/Chemical Methods," U.S. Environmental Protection Agency, SW-846 (Revised 1984).

TEKLAB

David D. Harry

#6 Meadow Heights Professional Park Collinsville, IL 62234 (618) 344-1004

June 17, 1985

PECEIVE

JATE OF ILLINUIL.

 F_f

REPORT #19-6

Andrews Environmental Engr., Inc. Project: Special Waste Testing

1320 South Fifth

Springfield, IL 62703

Fiat Allis

Springfield

ATTN: Mr. Douglas Andrews

Sample received: 06/03/85

Sample ID

Sample Date

Plating Tank #2

5/31/85

Lab ID #

50603-11

ANALYSIS RESULTS

Cyanide (Total)

Sulfide (Total)

10.7 1090 mg/kg <5 mg/kg

E P Toxicity

PARAMETER	CONCENTRATION in EXTRACT	
Arsenic Barium Cadmium Chromium, Total Lead Mercury Selenium Silver	0.25 <1 3240 1.4 1.2 <0.001 <0.005 <0.01	mg/1 mg/1 mg/1 mg/1 mg/1 mg/1

These tests were conducted in accordance with "Test Methods for Evaluating Solid Waste, Physical/Chemical Methods," U.S. Environmental Protection Agency, SW-846 (Revised 1984).

TEKLAB

David D.

#6 Meadow Heights Professional Park Collinsville, IL 62234 (618) 344-1004



June 17. 1985

REPORT #19-7

Andrews Environmental Engr., Inc. Project: Special Waste Testing

Springfield, IL 62703

1320 South Fifth

ATTN: Mr. Douglas Andrews

Fiat Allis Springfield

Sample received: 06/03/85

Sample ID Sample Date

Lab ID #

Plating Rinse Tank

5/31/85

50603-9

ANALYSIS RESULTS

Cyanide (Total) Sulfide (Total)

8.8 23 mg/kg (5 mã/kã

E P Toxicity

PARAMETER	CONCENTRATION <u>in EXTRACT</u>	
Arsenic Barium Cadmium Chromium, Total Lead Mercury Selenium Silver	<0.005 1.2 3.32 <0.03 <0.05 <0.001 <0.005 <0.01	mg/1 mg/1 mg/1 mg/1 mg/1 mg/1

These tests were conducted in accordance with "Test Methods for Evaluating Solid Waste, Physical/Chemical Methods," U.S. Environmental Protection Agency, SW-846 (Revised 1984).

TEKLAB

David D.

#6 Meadow Heights Professional Park Collinsville, IL 62234 (618) 344-1004

June 17, 1985

REPORT #19-8

Andrews Environmental Engr., Inc. Project: Special Waste Testing

1320 South Fifth

Springfield, IL 62703

Fiat Allis Springfield

ATTN: Mr. Douglas Andrews

Sample received: 06/03/85

Sample ID Sample Date

Acid Tank 5/31/85

Lab ID #

50603-12

ANALYSIS RESULTS

Cyanide (Total) Sulfide (Total)

5.1 23 mg/kg (5 mg/kg

E P Toxicity

PARAMETER	CONCENTRATION <u>in EXTRACT</u>	
Arsenic Barium Cadmium Chromium, Total Lead Mercury Selenium Silver	<0.005 <1 0.099 <0.03 <0.05 <0.001 <0.005 <0.005	mg/1 mg/1 mg/1 mg/1 mg/1 mg/1 mg/1

These tests were conducted in accordance with "Test Methods for Evaluating Solid Waste, Physical/Chemical Methods," U.S. Environmental Protection Agency, SW-846 (Revised 1984).

TEKLAB

David D.

Coloro Savier

SANGAMON CO. 16700000 Springfield / Fiat-A

February 28, 1985

JUN 0 3 1985
JEPA-DLPC

PECEIVED

BOD 1965

150% JUPO

Environmental Protection Agency (Land Polution) 2200 Churchill Road Springfield, Illinios

EN: 25773 of Illinois = 2570.

Dear Sir,

With the possibility of Fiat Allis closing the plant in the near future, I think that the City of Springfield should be made aware of some health hazards around the facility.

I am unable to reveal my sources or my name, so there can be no implication, but I have someinformation that is vital to the safety of the public.

With all of the publicity about PCB's, you should know that PCB's regularly leaked on the ground near the electrical substations throughout the plant.

There was Cyanide dumped near the heat treatment facilities, along with other industrial toxins throughout the general area.

I feel that someone in authority should be made aware of these problems, because if the area is ever developed for another use, for example, housing, these toxins could cause some devastating human problems.

Please do not let this go unheeded, for the sake of unsuspecting people. Clean-up can be successfully done to restore the land to safety levels again.

Do not take this as a vengeful or eccentric letter, I have absolutely nothing to gain by revealing this information. What you do with the information I have provided will have to be up to your conscience, I pray that it will be guided in the proper direction.

Sincerely,

A Concerned Human Being

MAY 23 Julis

IEPA-DLPC

EPA Region 5 Records Ctr.

JmC- pls have thus is instigited their me advised Bill 4/19 February 28, 1985

RECEIVED

JUN 0 3 1985

OWER EXECUTE

APR 11 1985

OFFICE OF THE GOVERNOR MAIL CONTROL

RECEIVED

APR 12 1985

Governor James Thompson Mansion 5th & Jackson Springfield, Illinios

IEPA-DLPC

Dear Sir,

C-85-45-C

With the possibility of Fiat Allis closing the plant in the near future, I think that the City of Springfield should be made aware of some health hazards around the facility.

I am unable to reveal my sources or my name, so there can be no implication, but I have some information that is vital to the safety of the public.

With all of the publicity about PCB's, you should know that PCB's regularly leaked on the ground near the electrical substations throughout the plant.

There was Cyanide dumped near the heat treatment facilities, along with other industrial toxins throughout the general area.

I feel that someone in authority should be made aware of these problems, because if the area is ever developed for another use, for example, housing, these toxins could cause some devastating human problems.

Please do not let this go unheeded, for the sake of unsuspecting people. Clean-up can be successfully done to restore the land to safety levels again.

Do not take this as a vengeful or eccentric letter, I have absolutely nothing to gain by revealing this information. What you do with the information I have provided will have to be up to your conscience, I pray that it will be guided in the proper direction.

Sincerely,

A Concerned Human Being

- IATE OF LALL.

RECEIVED

MAY 23 1985

IEPA-DLPC